

REDI-Sensor Buyers Guide Cont.

Part #	OE Part #	Application
SE53006	BBM237140, BBM237140B	Mazda
SE54187 TPMS Service Kit	31201796, 31280298, 312017960, 312802980, 4H231A189BA, 68001743AA through AB, C2C28472, LR010503, Mazda Cap N/A, Mazda Nut GN3A37141, Mazda Nut GS1D37141, Mazda Seal GN3A37142A, Mazda Seal Washer GN3A37143A, Mazda Valve Core N/A, RQH500480, Volvo Cap N/A, Volvo Nut 30748281, Volvo Nut 307482810, Volvo Seal N/A, Volvo Valve Core N/A, Volvo Washer N/A	Chrysler, Jaguar, Land Rover, Mazda, Mitsubishi, Volvo
SE54189 TPMS Service Kit, REDI-Sensor and OE Style	Hyundai Cap N/A, Hyundai Nut 529342L100, Hyundai Seal/Washer N/A, Hyundai Valve Core N/A, Kia Cap N/A, Kia Nut 529342L100, Kia Seal/Washer N/A, Kia Valve Core N/A	Chrysler, GM, Ford, Hyundai, Kia, Mazda, Mitsubishi, Nissan
SE57635 TPMS Valveless Sensor + Plastic Retaining Clip <small>(metal cradle/bracket and band not included)</small>	6F2A1A176AE, 6F2T1A150AE, 6F2Z1A189A, 6L2T1A150AA, 7L1Z1A189A, ZZC137140	Ford, Mazda
SE57772 TPMS Sensor Assembly	56029526AA, 68078861AA	Chrysler, Mitsubishi