

## REDI-Sensor Buyers Guide - September 2011

Part #	Application
<b>SE10001</b> <b>314.9/315</b> <b>MHz</b>	BUICK ALLURE 09-07; LACROSSE 11-07; LUCERNE 11-07; REGAL 11; BUICK TRUCK ENCLAVE 11-08; RAINIER 07-06; CADILLAC CTS 11-04; DTS 11-06; STS 11-05; XLR 09-04; CADILLAC TRUCK ESCALADE 11-07; SRX 11-04; CHEVROLET CAMARO 12-10; CAPRICE 11; COBALT 10-08; CORVETTE 11-05; CRUZE 11; HHR 11-08; IMPALA 11-06; MALIBU 11-08; MONTE CARLO 07-06; VOLT 11; CHEVROLET TRUCK EQUINOX 11-07; SSR 06; TAHOE 11-07; TRAILBLAZER 09-06; TRAVERSE 11-09; CHEVROLET TRUCK - 1/2 TON PICKUP AVALANCHE 11-07; SILVERADO 1500 11-07; CHEVROLET TRUCK - 1/2 TON SUBURBAN SUBURBAN 1500 11-07; CHEVROLET TRUCK - 1/2 TON VAN EXPRESS 1500 11-08; CHEVROLET TRUCK - MINIVAN UPLANDER 09-08; CHRYSLER 200 11; 300 07-05; PT CRUISER 10-08; SEBRING 10-08; CHRYSLER TRUCK ASPEN 09-07; PACIFICA 08-05; CHRYSLER TRUCK - MINIVAN TOWN & COUNTRY 09-04; DODGE AVENGER 11-08; CALIBER 11-07; CHARGER 07-06; MAGNUM 07-05; DODGE TRUCK DAKOTA 10-08; DURANGO 09-07; NITRO 11-07; DODGE TRUCK - MINI VAN CARAVAN 07-04; GRAND CARAVAN 09-04; FORD CROWN VICTORIA 11-07; FIESTA 11; FOCUS 12-07; FUSION 12-07; MUSTANG 12-07; TAURUS 11-08; TAURUS X 09-08; FORD TRUCK EDGE 11-07; ESCAPE 11-06; EXPEDITION 11-05; EXPLORER 11-06; EXPLORER SPORT TRAC 10-07; FLEX 12-09; RANGER 11-07; FORD TRUCK - 1/2 TON PICKUP F-150 11-07; FORD TRUCK - MINIVAN FREESTAR 07-04; TRANSIT CONNECT 11-10; GMC TRUCK ACADIA 11-07; ENVOY 09-05; TERRAIN 11-10; YUKON 11-07; YUKON XL 1500 11-07; GMC TRUCK - 1/2 TON PICKUP SIERRA 1500 11-07; SIERRA DENALI 10-07; GMC TRUCK - 1/2 TON VAN SAVANA 1500 11-08; HUMMER H2 09-08; HYUNDAI ACCENT 12; ELANTRA 11-10; GENESIS COUPE 11-10; SONATA 12-11; INFINITI G35 08-07; G37 10-08; M35 10-08; M45 10-08; Q45 06; INFINITI TRUCK EX35 10-08; FX35 10-07; FX45 08-07; FX50 10-09; QX56 10-07; ISUZU TRUCK ASCENDER 08-06; JEEP TRUCK COMMANDER 07-06; COMPASS 11-07; GRAND CHEROKEE 07-05; LIBERTY 11-05; PATRIOT 11-07; WRANGLER 12-08; KIA FORTE 11-10; OPTIMA 11; SOUL 11-10; KIA TRUCK SORENTO 12-11; LINCOLN MKS 11-09; MKZ 11-07; TOWN CAR 11-06; LINCOLN TRUCK MARK LT 08-07; MKT 11-10; MKX 11-07; NAVIGATOR 11-05; MAZDA 2 11; 3 11-04; 6 11-05; CX-7 11-07; CX-9 11-07; MX-5 MIATA 11-06; RX-8 11-04; MAZDA TRUCK 5 12-06; B2300 09-07; B3000 07; B4000 09-07; TRIBUTE 11-06; MERCURY GRAND MARQUIS 11-07; MILAN 11-07; MONTEGO 07-06; SABLE 09-08; MERCURY TRUCK MARINER 11-06; MONTEREY 07-04; MOUNTAINEER 10-06; MITSUBISHI ECLIPSE 11; GALANT 11-07; LANCER 11-08; MITSUBISHI TRUCK OUTLANDER 11-07; RAIDER 09-08; NISSAN 350Z 09-07; 370Z 10-09; ALTIMA 11-06; CUBE 11-09; GT-R 12-09; MAXIMA 11-07; SENTRA 11-07; VERSA 11-07; NISSAN TRUCK ARMADA 11-08; FRONTIER 11-08; JUKE 11; MURANO 12-07; PATHFINDER 11-07; QUEST 09-07; ROGUE 11-08; TITAN 11-07; XTERRA 11-07; PONTIAC G3 09; G5 10-08; G6 10-08; G8 09-08; GRAND PRIX 08-07; SOLSTICE 09-08; WAVE 08; PONTIAC TRUCK MONTANA 08; TORRENT 09-07; RAM TRUCK DAKOTA 11; SAAB TRUCK 9-7X 09-05; SATURN AURA 09-07; SKY 10-08; SATURN TRUCK OUTLOOK 10-07; VUE 10-07; SUZUKI FORENZA 08-07; KIZASHI 11-10; RENO 08-07; SUZUKI TRUCK XL-7 09-07
<b>SE10004</b> <b>433.92</b> <b>MHz</b>	CHRYSLER 300 08; 300M 04-02; CONCORDE 04-02; CROSSFIRE 08-04; PROWLER 02; CHRYSLER TRUCK PACIFICA 04; CHRYSLER TRUCK - MINIVAN TOWN & COUNTRY 10-02; VOYAGER 03-02; DODGE CHARGER 08; INTREPID 04-02; MAGNUM 08; VIPER 10-03; DODGE TRUCK JOURNEY 11-09; DODGE TRUCK - MINI VAN CARAVAN 03-02; GRAND CARAVAN 10-02; FORD TRUCK EXPEDITION 04-03; EXPLORER 05-02; ISUZU TRUCK RODEO 04; JEEP TRUCK COMMANDER 10-08; GRAND CHEROKEE 10-02; LIBERTY 09-04; LINCOLN TRUCK AVIATOR 05-03; NAVIGATOR 04-03; MERCURY TRUCK MOUNTAINEER 05-02; MITSUBISHI GALANT 06-04; MITSUBISHI TRUCK ENDEAVOR 06-04; VOLKSWAGEN TRUCK ROUTAN 10-09
<b>See <a href="http://www.redi-sensor.com">www.redi-sensor.com</a> for the latest application coverage expansions and for installation instructions and relearn procedures</b>	